## **Cost of Construction**

0031						
<u>Div.</u>	Section (portions of the Work)	New England	Construction	Notes		
1	GC General Conditions Permit fees Misc. General conditions Misc. General Requirements Waste management and disposal Post construction cleaning Sub-Total	\$ \$ \$ \$ \$ <b>\$</b>	By Owner 75,750 8,400 3,600 1,180 <b>88,930</b>	Supervision GR's. Temp Ofc / etc. Dumpsters Final Clean		
2	Concrete Foundation Formwork & Concrete Precast Sub-Total	\$ <b>\$</b>	10,108 <b>10,108</b>	Concrete floor polish BOH		
3	Wood, Plastics, and Composites Feature Wall (engineered wood) Sub-Total	\$	10,000			
4	Finish Carpentry Interior Doors Interior Casings & Trim Sub-Total	\$ \$	15,000 15,000 <b>15,000</b>	Trim / Finish Carpentry		
5	Millwork / Casework Cabinets & Countertops - Labor Install Cabinets & Countertops - Owner Furnished (allowance) Sub-Total	\$ \$ <b>\$</b>	56,737 - <b>56,737</b>	Millwork / Trim / Tops / etc. By Owner		
6	Doors  Marvin B.O.D. Door allowance  Marvin B.O.D. Window allowance  Sub-Total	\$ <b>\$</b>	3,550 <b>3,550</b>	Doors, Frames & Hardware		
7	Partitions (Wallboard & Metal Framing)  Metal stud framing 3 5/8" nominally 5/8" wallboard, taped & sanded  Sub-Total	\$ <b>\$</b>	31,036 <b>31,036</b>	Metal stud paritions / gyp Included		
8	Flooring Engineered Wood Floor Wall Base, Transitions & Thresholds Sub-Total	\$ <b>\$</b>	20,000 <b>20,000</b>	Flooring package Included		
9	Tile  Bathroom tile materials  Bathroom tile labor  Sub-Total	\$ \$	- - -	No tile No tile		
10	Painting  Magnetic wall painting of collage wall Interior Painting  Sub-Total	\$ <b>\$</b>	11,750 <b>11,750</b>	Included Includes Mural		
11	Specialties Hang Interior Wall Signage (metal lettering) provided by Owner Exterior Signage (backlit)- JRB working with SIgn Vendor Sub-Total	\$ \$ \$	- - -	By Owner By Owner		

12 Equipment

	Table Build Out (steel parts) on Casters (Owner Furnished) Steel Castoers (Owner furnished)	\$	7,500	Allowance	
	Toilet Room Accessories	\$	2,984		
	Sub-Total	\$	10,484		
13	Fire Protection Sprinkler Head Adjustments Sub-Total	\$ <b>\$</b>	7,000 <b>7,000</b>	Adjust exisitng	
	Jub-10tal	Ψ	1,000		
14	Plumbing Plumbing Rough-In Fixture Allowance Sub-Total	\$ \$ <b>\$</b>	39,900 5,000 <b>44,900</b>		
15	HVAC T-Stat and HVAC Controls HVAC Fan Coil Unit Ductwork & Resgisters Sub-Total	\$ <b>\$</b>	Included 83,500 Included 83,500		
16	Electrical Electrical Rough-In Lighting Fixture Allowance Alarm Tel/Data Sub-Total	\$ \$	54,014 15,000 <b>69,014</b>		
17	Exterior Improvements Vertial Fin Signage Sub-Total	\$ <b>\$</b>		By Owner	

## **Cost of Construction**

Total	\$ 462,009